### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of: David Arnold Luick : Date: July 29, 2008

Group Art Unit: 2113 : IBM Corporation

Examiner: C. S. McCarthy : Intellectual Property Law

Serial No.: 10/667,097 : Dept. 917, Bldg. 006-1

Filed: September 18, 2003 : 3605 Highway 52 North

Patent No.: 7,124,318 B2 : Rochester, MN 55901

Title: MULTIPLE PARALLEL PIPELINE

PROCESSOR HAVING SELF-REPAIRING CAPABILITY

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Dear Sir:

## CERTIFICATE OF ELECTRONIC TRANSMISSION

I hereby certify that this correspondence and any enclosures are being electronically transmitted via EFS-WEB on the date indicated below.

July 29, 2008	
Date	
/nancy j larson/	
Nancy I Larson	

#### PETITION UNDER 37 CFR 1.183 FOR CERTIFICATE OF CORRECTION

In the matter of Patent Number 7,124,318 B2 which issued on October 17, 2006, a careful check of the same against the file of the attorney shows errors in the patent chargeable to the Official Printer, as shown on the attached Certificate of Correction.

It is requested that the attached Certificate of Correction be certified and issued to International Business Machines Corporation, Rochester, Minnesota 55901.

Respectfully submitted,

By\_\_\_\_/robert r williams/\_\_\_\_

Telephone: (507) 253-2761 Robert R. Williams
Fax No.: (507) 253-2382 Consulting Patent Agent
Registration No.: 48,395

Docket No.: ROC920030200US1

Serial No.: 10/667.097

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page	1	of	1
raut		U	

PATENT NO. : 7,124,318 B2 APPLICATION NO.: 10/667,097

ISSUE DATE : October 17, 2006

INVENTOR(S) : David Arnold Luick

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### IN THE CLAIMS:

Claim 1, Column 16, Line 41: "pipelines." should be --pipelines;

wherein said plurality of pipelines is arranged in an array;

wherein said control logic, responsive to detection of a failure in said first pipeline, causes data intended for processing by said first pipeline to be processed by said second pipeline, said second pipeline being physically adjacent said first pipeline in said array; and

wherein said control logic, responsive to detection of a failure in said first pipeline, further causes data intended for processing by said second pipeline to be processed by a third pipeline of said plurality of parallel pipelines, said third pipeline being physically adjacent said second pipeline in said array.--

Claim 11, Column 18, Line 3: "pipelines." should be -pipelines;

wherein said plurality of pipelines is arranged in an array;

wherein said control logic, responsive to detection of a failure in said first pipeline, causes data intended for processing by said first pipeline to be processed by said second pipeline, said second pipeline being physically adjacent said first pipeline in said array; and

wherein said control logic, responsive to detection of a failure in said first pipeline, further causes data intended for processing by said second pipeline to be processed by a third pipeline of said plurality of parallel pipelines, said third pipeline being physically adjacent said second pipeline in said array.--

MAILING ADDRESS OF SENDER (Please do not use customer number below):

IBM Corporation - Dept. 917 3605 Highway 52 North Rochester, MN 55901

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.